M18P-D0500N-CZ9P4UE

Photoelectric Sensor

M18 Prox-Style Photoelectric - Diffuse



Diagram

Note: The product images shown may change over time as products are updated.

Part Number

M18P-D0500N-CZ9P4UE

Features


Photoelectric sensors are used in virtually any manufacturing process with moving parts to detect products, machine parts, and a wide variety of moving objects.

For additional information, contact HTM Sensors at 800-644-1756 or service@htmsensors.com

Connection

SENSORS

DC Connector (M12)





Technical Data

8.1. 2. 3 or RFI>3 V/m (in 30-1000 KV (contact)
or 10-55 Hz, 1.0 mm amplitude in x, in. IEC 60947-5-2, Part 7.4.1 or 30 g,
ins for six time each

In the USA: 1889 Maryland Ave., Niagara Falls, NY 14305 In Canada: 3419 Mainway, Burlington, ON L7M 1A9 Toll Free: 1-800-644-1756 • Fax: 888-283-2127 service@htmsensors.com

htmsensors.com